## Certificate

Standard **ISO 9001:2015** 

Certificate Registr. No. 01 100 98061

Certificate Holder: **GESTAMP METALBAGES, S.A.** 

C/Les Arenes, 1 PI Santa Anna li

08251 Santpedor

Spain

including the branch offices according to annex

Scope: Design and production of metallic chassis parts and body parts

by cold stamping, welding, assembly and painting.

Proof has been furnished by means of an audit that the

requirements of ISO 9001:2015 are met.

Validity: The certificate is valid from 2021-02-13 until 2024-02-12.

First certification 2018

2021-06-29

TÜV Rheinland Cert GmbH Am Grauen Stein · 51105 Köln









## Annex to certificate

Standard ISO 9001:2015

Certificate Registr. No. 01 100 98061

No.	Location	Scope
/02	c/o GESTAMP ABRERA, S.A. C. Doctor Fleming, 9-13 P. I. Ca N'estella 08635 Sant Esteve Sesrovires Spain	Production of metallic car body and chassis parts by cold stamping, hot stamping and welding.
/03	c/o Gestamp Navarra, SA Polígono Industrial Arazuri-Orkoien, calle C 31160 Orkoien (Navarra) Spain	Production of metallic car body and chassis parts by stamping, hydroforming, welding & shotpeening.
/05	c/o GESTAMP ARAGON, S.A. P.I El Pradillo, General Motors 6 50690 Pedrola (Zaragoza) Spain	Production of metallic car body and chassis parts by cold stamping, hot stamping and welding.
/09	c/o GESTAMP METALBAGES, S.A. Polig. Ind. Santa Anna li Les Arenes, 1 08251 Santpedor Spain	Design and production of metallic chassis parts and production of metallic body parts by cold stamping, welding and painting.
/15	c/o GESTAMP MANUFACTURING AUTOCHASIS, S.L. Pol.Ind. El Pradillo, C/ Aneto 5 50690 Pedrola Spain	Desing and manufacture of metallic systems and components by welding, painting and assembly.
		1:0/2
	2021-06-29	TÜV Rheinland Cert

Page 1 of 1

**GmbH** 

